

Itronix (Husky) FS2 2018583-008 Release

This version includes bug fixes for our 2018583-007 version. The following are some of the highlights.

1. CHANGED COLLECT FOR XSERIES AND UFLO TO DETECT AND FIX BLOCK COUNT PROBLEM. This corrects the DB2 collection problem for the MicroFLO and XSeries products. Reference ABB Technical bulletin #110 for details.

We appreciate your choice of Totalflow and want to make this software the best it can be in meeting your operational needs. We would like to hear from you if you have any comments or problems. You can contact us at the following address.

Totalflow Customer Service
7051 Industrial Blvd.
Bartlesville, OK 74006

or phone 1-800-442-3097