

PCCU32 Service Pack 3.10.5

History:

Update 2 includes:

- this file pccu_sp2.txt
- pccu32.exe
- tfltopl.dll
- tfccu32.dll
- tfttrndl.dll
- tfarpt.dll
- tfspread.dll
- fcumentry.ini
- aiumentry.ini
- fcumon.ini
- fcumonit.ini
- eioumentry.ini

Version 3.10.5 Fixed:

- Stored correct year number for trend database, spread sheet.
- Fixed to handle contract hour for RTU properly.

Version 3.10.4 Fixed:

- Added support for new turbine meters.
- Fixed problem with old database flow record dates derived from event log.

Version 3.10.3 Fixed:

- Fixed problem with AIU Satellite Bus Isolation switch.
- Fixed problem with AIU monitor mode ID list.
- Fixed problem with AIU stream setup hourly/cycle switch.
- Fixed problem with AIU edit stream analyzer/stream number changes.

Version 3.10.2 Fixed:

- Show Faux on Full Stream Wet Gas Meters
- Display correctly pipe tap and flange tap selection in constants tab/entry.
- Temperature compensation for turbine meters.
- Turn on valve control when valve control is selected.
- Recalculate Fb when tap type is changed.
- Prevent importing laptop files from bad floppy disks.
- Add option support for tank gauge and Tc Bus.
- Show Contract Barometric Press for gauge meters
- Add Continuous Update check box to Calibrate/Cal Check entry dialog
- Add AIU support for Satellite Bus Isolation,

User index codes, and Log Interval.

- Ask the users to insert floppy disk into drive A when saving data to floppy.
- Fix Custom Display download problem.